



Parts Tip

Parts Tip Number: PT157

Date: December 15, 2004

Model (s) Affected :	AL1045 AL1215 AL1216 AL1217 AL1218 AL1225 AL1226 AL1255 AL1456 AL1457 AL1458 AL1530CS AL1540CS AL1551CS AL1555 AL1631 AL1641CS AL1645CS SN1045 SN1255 SN1456 SN1555 AR122E AR123E AR152E AR153E AR157E AR5012
Subject:	Change to Carriage unit

Symptom or Problem:	
Cause:	
Solution or action to resolve issue:	Please use the information below. Please note that when DUNT-0276QSZZ and DUNT-0276QS11 are no longer available, you will have to use DUNT-0404QSZZ. When you use DUNT-0404QSZZ you will also have to remove all items in BLUE color on this document.

DCE-522R

P/G Number	Current Part Number	New Part Number	Description
10 -6	DUNT-0276QSZZ	DUNT-0276QS11	Carriage unit
10 -39	PSHEZ0389QSZZ	PSHEZ0389QSZ1	Scanner sheet
11 -2	DHAI-0282QSZZ	DHAI-0282QSZ1	LSU harness
10 -42	PCUSU0026QSZZ	--	Core cushion
10 -41	RCORF0020QSZZ	--	FCC Core
15 -27	RCORF0021QSZZ	--	Core
15 -28	RCORF0034FCZZ	--	Core

P/G Number	Current Part Number	New Part Number	Description
10 -6	DUNT-0276QS11	DUNT-0404QSZZ	Carriage unit
10 -47	PMLT-0068QSZZ	--	Core holder
10 -45	PSHEZ0401QSZ1	--	Scanner core sheet
10 -	LFX-0025QSZZ	--	CCD harness holder
15 -22	PSHEZ0390QSZZ	--	PWB holder sheet